



August 04, 2026

To,
Listing Compliance Department
BSE Limited
Phiroze Jeejeebhoy Towers,
Dalal Street, Mumbai – 400001
BSE Scrip Code: 544029

Listing & Compliance Department
National Stock Exchange of India Limited
Exchange Plaza, 5th Floor
Plot No. C/1, “G” Block
Bandra-Kurla Complex
Bandra (E), Mumbai – 400 051
Symbol: GANDHAR

Subject: Intimation pursuant to Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 – Impact on Operations due to Flooding Caused by Unprecedented Heavy Rains at the Company's Silvassa Plant

Dear Sir(s)/Madam(s),

This is in continuation to our earlier intimation dated July 24, 2026 submitted to the Stock Exchanges and pursuant to Regulation 30 of the SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015, regarding the impact on operations of the Company's manufacturing facility located at Silvassa, Dadra and Nagar Haveli, U.T. – 396230, due to unprecedented heavy rainfall and flood-like conditions.

The Company wishes to inform that operations at the said manufacturing facility have resumed. The Company is currently assessing the situation and evaluating the impact, arising from the heavy rainfall and flood-like conditions experienced as previously intimated in its communication dated July 24, 2026. The Company has insurance coverage and the incident has been duly intimated to the insurance company.

The details as required under Listing regulations are provided in Annexure A enclosed herewith.

Kindly take the above information on record.

Thanking you.

Yours faithfully,

For **Gandhar Oil Refinery (India) Ltd**

Binal Khosla
Company Secretary & Compliance Officer
Mem. No.: A29802

Encl.: Annexure A

The details required under Regulation 30 of Listing Regulations read with the SEBI circular bearing reference number HO/49/14/14(7)2025-CFD-POD2/I/3762/2026 dated January 30, 2026 for disruption of operations of any one or more units or division of the listed entity due to natural calamity (earthquake, flood, fire etc.), force majeure or events such as strikes, lockouts etc. are as under:

Sr. No.	Particulars	Details
1.	Expected quantum of loss/damage caused	The Company is currently assessing the extent of loss/damage, if any, caused due to the heavy rainfall and flood-like conditions at its manufacturing facility located at Silvassa, Dadra and Nagar Haveli, U.T. – 396230.
2.	Whether loss/damage covered by insurance or not including amount;	The Company has insurance coverage and the incident has been intimated to the insurance company.
3.	Estimated impact on the production/operations in case of strikes/lock outs;	Not Applicable
4.	Factory/Unit where the strike/lock out takes place including reasons for such strike	Not Applicable
5.	Steps taken for restoration and normalisation of operations	The Company has undertaken necessary measures for restoration of operations at its manufacturing facility located at Silvassa, Dadra and Nagar Haveli, U.T. – 396230. Necessary cleaning, inspection, repair and remedial measures have been completed to ensure safe and smooth functioning of the facility. The Company has resumed operations and is closely monitoring the situation to achieve normalisation of operations.

Registered Office

18th Floor, DLH Park, S.V.Road, Near MTNL
Goregaon West, Mumbai 400 062 India
CIN : L23200MH1992PLC068905
T: +91 22 4063 5600 F: + 91 22 4063 5601
E-mail: sales@gandharoil.com
Website : www.gandharoil.com